Report Date: 12/05/2006

EAGLE CREEK AVIATION SERVICES C.A.L.M. Auxiliary Inspection Report

Page: 1

Auxiliary Se	rial # BVA6321	Auxiliary	Hours:	425.10
Auxiliary	Model: HC-B3TN-5FL	Auxiliary	Cycles	390.00

ATA Code Inspection	Item	W/O #	Based on	Service Life	Last Inspection Date	Last Inspection Time	Since Last Inspection	Due At	Period to Next Insp.
: : PROPELLER OVERHAUL INTERVAL (HOURS/MONTHS) INSPECT IAW PROPELLER OVERHAUL MANUAL			Hours Cycles Days	3000.00	11/27/2002	0.00	425.10	3000.00	2574.90
- HOI EOT IAW THOI ELLEN OVERTIAGE MANGAE	-		Months	60	11/27/2002			11/30/2007	
: ; AD 83-08-01 R1 HARTZELL PROP ATTACH BOLTS @ EACH ACC	2 ESS		Hours Cycles Days Months						